

____} }




FIG. 2




FIG. 3




FIG. 4

VC-4 FRAME CARRYING THREE VC-3 FRAMES TO FORM AU-4

(TUG-3)*3+(VC-4 POINTER)=VC-4	261	
	9 10 11 12	O ·
-	=	m
	10	⋖
		5
	œ	5
	5 · 6 7	H1 H1 J1 L1
	9 .	도
		도
	4	
Ξ	က	
4 PC	7	
VC-4 POH	_	

STUFF COLUMNS

FIG. 5




FIG. 6





FIG. 7






FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 1.




FIG. 18

STM-4 FRAME OVERHEAD FORMAT USED INSIDE THE UNIT

#12		-	-	H3		-	1	-	
#3	1	1	Ι	Н3			-	1	1
#2	١	1	_	Н3	1	1			-
#1	_		-	Н3	-		1	1	-
#12	. A2			Н2			ı	_	
#3	A2	1	1	H2	-		1	-	1
#5	Å2	ı		Н2	1	ı	I	1	ı
#1	A2	E1	ı	H2	1	ı	1	-	-
#12	A1		•	H1		ı	1	-	1
#3	A1		ŀ	H1	_	-	1	1	I
#5	A1		ı	H	ı	1	1	1	1
#1	A1	B1	-	H1		I	1	1	1

FIG. 19

BIT#	DEFINITION	STATE			
1, 2	UNUSED	0			
3	AU-4-16c (STS-48c)	1: CONCATENATED			
4	AU-4-4c (STS-12c)	1: CONCATENATED			
5	AU-4(STS-3c) #4	1: CONCATENATED			
6	AU-4(STS-3c) #3	1: CONCATENATED			
7	AU-4(STS-3c) #2	1: CONCATENATED			
8	AU-4(STS-3c) #1	1: CONCATENATED			

FIG. 20




FIG. 2




FIG. 22





FIG. 23






FIG. 25




FIG. 26




FIG. 27




FIG. 28